

APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		

1/3

FIG. 1





FIG. 2



09810794-05101

2/3

FIG. 3





FIG. 5




APPROVED	O.G. FIG.	
BY	CLASS	SUBCLAS
DRAFTSMAN		

Paul W. Romig, et al.  
 Methods For Preventing Contamination Of Products  
 From Product Labels And Adhesives

3/3

FIG. 4






FIG. 1

200




FIG. 2

315  
Binding Agent







FIG. 3



400




FIG. 4

500




FIG. 5